1-190A031

LAW OFFICES

McCarthy, Sweeney & Harkaway, P. C.

1750 Pennsylvania Ave.,  $N.\ W$ 

WASHINGTON, D C. 20006

Telephone (202) 393-5710 Telecopier (202) 393-5721

Douglas M. Canter John M. Cutler, Jr William I. Harkaway Steven J Kalish Harvey L. Reiter Daniel J. Sweeney Kathleen L. Mazure

ANDREW P GOLDSTEIN Counsel

CHARLES J. McCARTHY
Counsel

July 9, 1991

PRED 1425

JUL 9 1991 -2 35 PM

Interstate Commerce Commission 12th & Constitution Avenue, N.W. Washington, DC 20423

INTERSTATE COMMERCE COMMISSION

Attention:

Mildred Lee.

Dear Ms. Lee:

Enclosed for filing recordation with the Commission are a certified true copy and one counter-part of the document described below, to be recorded pursuant to Section 11303 of the Interstate Commerce Act, 49 U.S.C. § 11303.

This document is a CERTIFICATION OF AMENDMENT OF EQUIPMENT IDENTIFYING MARKS by Louis Dreyfus Corporation. The primary document to which this document is connected is Recordation No. 17419.

The name and address of the sole party to this document is as follows:

Louis Dreyfus Corporation 10 Westport Road Wilton, CT 06897-0810

The equipment covered by this document is two hundred ten (210) covered hopper cars bearing markings as shown in Exhibit A of the Certificate.

This document should be indexed as:

Certification of 210 Identifying Marks dated July 8, 1991, by Louis Dreyfus Corporation.

This document should be cross-indexed to Nos. 16001 and 16002.

Courter part - Males 1

Also enclosed please find a check in the amount of \$15.00 as the filing fee required by 49 C.F.R. 1177.3.

Sincerely,

Andrew P. Goldstein

Attorney for

Louis Dreyfus Corporation

Made P. Colster

**Enclosures** 

APG/rmm

· }\_-

estrenation no 17419 Partiti

JUL 9 1991 -2 35 PM

## INTERSTATE CONTINUENCE COMMISSION CERTIFICATE OF AMENDMENT OF EQUIPMENT IDENTIFYING MARKS

This CERTIFICATE is made this 8th day of July 1991 by Louis Dreyfus Corporation.

## WITNESSETH:

WHEREAS, Louis Dreyfus Corporation is the lawful Lessee of certain freight cars, originally bearing identifying marks as set forth in Exhibit A attached hereto (the "Equipment"); and

WHEREAS, Louis Dreyfus Corporation desires to certify that the identifying marks of the units of Equipment, some of which were heretofore subject to recordation with the Interstate Commerce Commission pursuant to 49 U.S.C. § 11303 under Recordation Nos. 16001 and 16002, have been amended as set forth in Exhibit A.

NOW, THEREFORE, in consideration of the premises, Louis
Dreyfus Corporation does hereby certify that the current
identifying marks of the Equipment are as set forth in Exhibit A.

The 210 cars covered under of lease were changed as follows:

1	LDCX	20227	restenciled	to	UMP	120227
2	LDCX	20309	restenciled	to	UMP	20309
3	LDCX	20319	restenciled	to	UMP	20319
4	<b>LDCX</b>	20327	restenciled	to	UMP	20327
5	LDCX	20404	restenciled	to	UMP	120404
6	<b>LDCX</b>	20426	restenciled	to	UMP	20426
7	<b>LDCX</b>	20440	restenciled	to	UMP	20440
8	LDCX	20442	restenciled	to	UMP	20442
9	LDCX	20450	restenciled	to	UMP	120450
10	LDCX	20462	restenciled	to	UMP	20462
11	LDCX	20464	restenciled	to	UMP	20464
12	LDCX	20467	restenciled	to	UMP	120467
13	LDCX	20473	restenciled	to	UMP	120473
14	LDCX	20483	restenciled	to	UMP	20483
15	LDCX	20500	restenciled	to	UMP	120500
16	LDCX	20504	restenciled	to	UMP	20504
17	LDCX	20521	restenciled	to	UMP	120521
18	LDCX	20526	restenciled	to	UMP	20526
19	LDCX	20527	restenciled	to	UMP	20527
20	LDCX	20533	restenciled	to	UMP	120533
21	LDCX	20534	restenciled	to	UMP	20534
22	LDCX	20544	restenciled	to	UMP	20544
23	LDCX	20556	restenciled	to	UMP	20556
24	LDCX	20557	restenciled	to	UMP	20557
25	LDCX	20560	restenciled	to	UMP	20560
26	LDCX	20564	restenciled		UMP	20564
27	LDCX	20565	restenciled	to	UMP	120565
28	LDCX	20586	restenciled		UMP	20586
29	LDCX	20595	restenciled	to	UMP	20595
30	LDCX	20596	restenciled	to	UMP	20596
31	LDCX	20597	restenciled	to	UMP	120597
32	LDCX	20598	restenciled	to	UMP	20598
33	LDCX	20599	restenciled	to	UMP	120599
34	LDCX	20600	restenciled	to	UMP	20600
35	LDCX	20601	restenciled	to	UMP	20601
36	LDCX	20602	restenciled	to	UMP	20602
37	LDCX	20603		to	UMP	20603
38	LDCX	20606	restenciled	to	UMP	20606
39	LDCX	20608	restenciled	to	UMP	20608
40	LDCX	20609	restenciled	to	UMP	20609
41	LDCX	20611	restenciled	to	UMP	20611
42	LDCX	20612	restenciled	to	UMP	20612
43	LDCX	20615	restenciled	to	UMP	20615
44	LDCX	20631	restenciled	to	UMP	20631
45	LDCX	20636	restenciled	to	UMP	20636
46	LDCX	20640	restenciled	to	UMP	120640
47	LDCX	20644	restenciled	to	UMP	20644
48	LDCX	20653	restenciled	to	UMP	20653
49	<b>LDCX</b>	20654	restenciled	to	UMP	20654
50	LDCX	20666	restenciled	to	UMP	20666
51	LDCX	20671	restenciled	to	UMP	20671
52	<b>LDCX</b>	20672	restenciled	to	UMP	120672
53	<b>LDCX</b>	20673	restenciled	to	UMP	120673
54	LDCX	20675	restenciled	to	UMP	2 <b>067</b> 5

55	LDCX	20676	restenciled	to	UMP	20676
56	LDCX	20692	restenciled	to	UMP	20692
57	LDCX	20695	restenciled	to	UMP	20695
58	LDCX	20697	restenciled	to	UMP	20697
59	LDCX	20700	restenciled	to	UMP	20700
60	LDCX	20710	restenciled	to	UMP	20710
61	LDCX	20712	restenciled	to	UMP	20712
62	LDCX	20713	restenciled	to	UMP	20713
63	LDCX	20714	restenciled	to	UMP	20714
64	LDCX	20715	restenciled	to	UMP	20715
65	LDCX	20716	restenciled	to	UMP	20716
66	LDCX	20717	restenciled	to	UMP	20717
	LDCX	20718	restenciled	to	UMP	20718
	<b>LDCX</b>	20719	restenciled	to	UMP	20719
69	LDCX	20720	restenciled	to	UMP	20720
	LDCX	20721	restenciled		UMP	20721
	LDCX	20722	restenciled		UMP	20722
	LDCX	20723	restenciled		UMP	20723
	LDCX	20724	restenciled		UMP	20724
	<b>LDCX</b>	20725	restenciled		UMP	20725
	LDCX	20726	restenciled		UMP	20726
	LDCX	20728	restenciled		UMP	20728
	LDCX	20729	restenciled		UMP	20729
	LDCX	20730	restenciled		UMP	20730
	LDCX	20731	restenciled		UMP	20731
	<b>LDCX</b>	20732	restenciled		UMP	20732
	LDCX	20733	restenciled		UMP	20733
	LDCX	20734	restenciled		UMP	20734
	LDCX	20735	restenciled		UMP	20735
	LDCX	20736	restenciled		UMP	20736
	LDCX	20737	restenciled		UMP	20737
	<b>LDCX</b>	20738	restenciled		UMP	20738
	LDCX	20739	restenciled		UMP	20739
	LDCX	20740	restenciled		UMP	20740
	LDCX	20741	restenciled		UMP	20741
	LDCX	20742	restenciled		UMP	20742
	LDCX	20744	restenciled		UMP	20744 20745
	LDCX	20745	restenciled restenciled		UMP UMP	20745
	LDCX LDCX	20746 20747	restenciled		UMP	20747
	LDCX	20748	restenciled		UMP	20748
	LDCX	20749	restenciled		UMP	20749
	LDCX	20750	restenciled		UMP	20750
	LDCX	20751	restenciled		UMP	20751
	LDCX	20752	restenciled		UMP	20752
	LDCX	20753	restenciled		UMP	20753
	LDCX	20755	restenciled		UMP	20755
	LDCX	20756	restenciled		UMP	20756
	LDCX	20757	restenciled		UMP	20757
	LDCX	20758	restenciled		UMP	20758
	LDCX	20759	restenciled		UMP	20759
	LDCX	20760	restenciled	to	UMP	20760
	LDCX	20761	restenciled	to	UMP	20761
	LDCX	20762	restenciled	to	UMP	20762
	LDCX	20763	restenciled	to	UMP	20763
	LDCX	20764	restenciled	to	UMP	20764

. . . . .

.\*

111	LDCX	20765	restenciled	to	UMP	20765
112	LDCX	20766	restenciled	to	UMP	20766
113	LDCX	20767	restenciled	to	UMP	20767
114	LDCX	20768	restenciled	to	UMP	20768
115	LDCX	20769	restenciled	to	UMP	20769
116	LDCX	20770	restenciled	to	UMP	20770
117	LDCX	20771	restenciled	to	UMP	20771
118	LDCX	20772	restenciled	to	UMP	20772
119	LDCX	20773	restenciled	to	UMP	20773
120	LDCX	20774	restenciled	to	UMP	20774
121	LDCX	20775	restenciled	to	UMP	20775
122	LDCX	20776	restenciled	to	UMP	20776
123	LDCX	20777	restenciled	to	UMP	20777
124	LDCX	20778	restenciled	to	UMP	20778
125	LDCX	20779	restenciled	to	UMP	20779
126	LDCX	20780	restenciled	to	UMP	20780
127	LDCX	20781	restenciled	to	UMP	20781
128	LDCX	20782	restenciled	to	UMP	20782
129	LDCX	20783	restenciled	to	UMP	20783
130	LDCX	20784	restenciled	to	UMP	20784
131	LDCX	20785	restenciled	to	UMP	20785
132	LDCX	20786	restenciled	to	UMP	20786
133	LDCX	20787	restenciled	to	UMP	20787
134	LDCX	20788	restenciled	to	UMP	20788
135	LDCX	20789	restenciled	to	UMP	20789
136	LDCX	20792	restenciled	to	UMP	20792
137	LDCX	20793	restenciled	to	UMP	20793
138	LDCX	20794	restenciled	to	UMP	20794
139	LDCX	20795	restenciled	to	UMP	20795
140	LDCX	20796	restenciled	to	UMP	20796
141	LDCX	20797	restenciled	to	UMP	20797
142	LDCX	20798	restenciled	to	UMP	20798
143	LDCX	20799	restenciled	to	UMP	20799
144	LDCX	20800	restenciled	to	UMP	20800
145	LDCX	20801	restenciled	to	UMP	20801
146	LDCX	20802	restenciled	to	UMP	20802
147	LDCX	20803	restenciled	to	UMP	20803
148	LDCX	20804	restenciled	to	UMP	20804
149	LDCX	20805	restenciled	to	UMP	20805
150	LDCX	20806	restenciled	to	UMP	20806
151	LDCX	20807	restenciled	to	UMP	20807
152	LDCX	20808	restenciled	to	UMP	20808
153	LDCX	20809	restenciled	to	UMP	20809
154	LDCX	20810	restenciled	to	UMP	20810
155	LDCX	20811	restenciled	to	UMP	20811
156	LDCX	20812	restenciled	to	UMP	20812
157	LDCX	20814	restenciled	to	UMP	20814
158	LDCX	20815	restenciled	to	UMP	20815
159	LDCX	20816	restenciled	to	UMP	20816
160	LDCX	20817	restenciled	to	UMP	20817
161	LDCX	20818	restenciled	to	UMP	20818 20819
162	LDCX	20819	restenciled	to	UMP	20819
163	LDCX	20820	restenciled	to	UMP	20820
164	LDCX	20821	restenciled	to	UMP	
165	LDCX	20822	restenciled	to	UMP	20822 20823
166	LDCX	20823	restenciled	ισ	UMP	ZU0Z3

. . .

167	LDCX	20824	restenciled	to	UMP	20824
168	LDCX	20825	restenciled	to	UMP	20825
169	LDCX	20826	restenciled	to	UMP	20826
170	LDCX	20827	restenciled	to	UMP	20827
171	LDCX	20828	restenciled	to	UMP	20828
172	LDCX	20829	restenciled	to	UMP	20829
173	LDCX	20830	restenciled	to	UMP	20830
174	LDCX	20831	restenciled	to	UMP	20831
175	LDCX	20832	restenciled	to	UMP	20832
176	LDCX	20833	restenciled	to	UMP	20833
177	LDCX	20834	restenciled	to	UMP	20834
178	LDCX	20835	restenciled	to	UMP	20835
179	LDCX	20836	restenciled	to	UMP	20836
180	LDCX	20837	restenciled	to	UMP	20837
181	LDCX	20838	restenciled	to	UMP	20838
182	LDCX	20839	restenciled	to	UMP	20839
183	LDCX	20840	restenciled	to	UMP	20840
184	LDCX	20842	restenciled	to	UMP	20842
185	LDCX	20843	restenciled	to	UMP	20843
186	LDCX	20844	restenciled	to	UMP	20844
187	LDCX	20845	restenciled	to	UMP	20845
188	<b>LDCX</b>	20846	restenciled	to	UMP	20846
189	LDCX	20847	restenciled	to	UMP	20847
190	LDCX	20848	restenciled	to	UMP	20848
191	LDCX	20849	restenciled	to	UMP	20849
192	LDCX	20850	restenciled	to	UMP	20850
193	LDCX	20851	restenciled	to	UMP	20851
194	LDCX	20852	restenciled	to	UMP	20852
195	LDCX	20856	restenciled	to	UMP	20856
196	LDCX	20857	restenciled	to	UMP	20857
197	LDCX	20881	restenciled	to	UMP	20881
198	LDCX	20887	restenciled	to	UMP	20887
199	LDCX	20888	restenciled	to	UMP	20888
200	LDCX	20967	restenciled	to	UMP	20967
201	LDCX	20970	restenciled	to	UMP	20970
202	LDCX	20979	restenciled	to	UMP	20979
	LDCX	20986	restenciled		UMP	20986
	LDCX	20989	restenciled	to	UMP	20989
	LDCX	21000	restenciled		UMP	21000
	LDCX	21003	restenciled		UMP	21003
	LDCX	21018		to	UMP	21018
	LDCX	21022	restenciled		UMP	21022
	LDCX	21034	restenciled		UMP	21034
210	LDCX	21045	restenciled	to	UMP	21045

## LOUIS DREYFUS CORPORATION

By: \_\_\_\_\_\_\_ Vice President \_\_\_\_\_

STATE OF CONNECTICUT
COUNTY OF FAIRFIELD

On this 8th day of July 1991, before me personally appeared R. Bruce Radley, who being by me duly sworn, says that he is a Vice President of Louis Dreyfus Corporation and that the seal affixed to the foregoing instrument was signed on behalf of said corporation by authority of the Board of Directors of said corporation.

Notary Public

My Commission Expires: 3-31-9

ESTABLISHED IN 174/9- B

CERTIFICATE

JUL 9 1991 -2 35 PM

INTERSTATE CONTINENCE COMMISSION

I, Andrew P. Goldstein, hereby certify that I am an attorney duly admitted in the District of Columbia, and am a member in good standing of the Bar of the District of Columbia, and that I have, this 9th day of July 1991, compared the enclosed copy of a certain CERTIFICATE OF AMENDMENT OF EQUIPMENT IDENTIFYING MARKS, dated July 8, 1991, by Louis Dreyfus Corporation, with the original document and certify that it is complete and identical in all respects to the original document.

Andrew P. Goldstein

Sworn to and subscribed before me this 9th day of July 1991.

Dona J. Galmer My Commission expires: 3/14/93